INTELLITOUCH® AUTOMATION REPLACEMENT PARTS

Part No.	Description
NEW INTELLITOUCH AUTOMATION REPLACEMENT PARTS	
521227	Replacement Load Center Diog5667077 (em11.9S (em11.9S (em11.9S (em11.99 (eem11. Td[R)10.5 (ep)-1.5 (254.9 (2)-37.1 (72 (d)12.02299 10.0217.9 5A)1.85 Td7 0 (Z[R)10.5 .7 (E)-
	works with all versions
520830Z	MobileTouch II Transformer with Cord
520834Z	MobileTouch II Charging Cradle
520815Z	MobileTouch II Battery & Door
520191	MobileTouch I Transformer with Cord
520217	Antenna For Mobiletouch 1 Transceiver
520907	MobileTouch II Wireless Remote Replacement
520946Z	Mobiletouch II Transceiver Circuit Board With Attached Antenna
8520031Z	Repl. Circuit Breaker (3 Amp)
521245	QuickTouch II Remote Replacement
521246	QuickTouch II Receiver Replacement
520658	Indoor Control Panel Labels (Qty. 10)
520283	Outdoor Panel Labels (Qty. 10)
521227	New Load Center Door w/ET & IT Labels (Qty. 10)
520344	iS10 Label Set (Qty. 10)
522082	iS4 Label Set (Qty. 10) - New Style
520173	iS4 Label Set (Qty. 10) - Old Style

CALIFORNIA PROPOSITION 65 WARNING

⚠ **WARNING:** Cancer and Reproductive Harm.
⚠ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.

www.p65warnings.ca.gov. P/N 20174.A